

MEDICAL

TECHNICAL SERVICE BULLETIN #3

Product: Fabius Tiro

Date: April 20, 2004

Re: Software Release – 2.10A

Reference Doc: Product Bulletin # 164, SP00297

Reason/Rational: Enhancement

Solution/Procedure: Perform Software 2.10A upgrade on all Fabius Tiro units.

Complete the Return Form (attached) and return to DMI/DS within

7 days of account completion.

Devices affected: All

Timing/When: At customer request, next service or Periodic Manufacturer's

Service

Additional Info: For details regarding Software 2.10a see Product Bulletin # 164

Cost: Software upgrades to 2.10A are available to Fabius Tiro

customers at no charge.

Ordering Info/Parts: Kit – S/W Upgrade V2.10A – P/N 4118734-001.

Distribution: DrägerService N.A. & all Authorized Service Organizations

DrägerService 3122 Commerce Drive Telford, PA 18969 Tel: (215) 721-5402 (800) 543-5047 Fax: (215) 723-5935

Web: www.draegermedical.com

DrägerService is a division of Draeger Medical, Inc.



Product: Fabius Tiro

Re: TSB #3

Return Form - Software 2.10A Upgrade

Distributor:		Customer:	
Country:	Address:		
		City:	
N	/lachine S/N	Machine S/N	Machine S/N
_ _ _			
_ _			
_			
_ _ _			
<u> </u>			
_ _ _			
_ _			
Fax To: DrägerService Attn: Al Myers (215) 721-5784		Date of Update Signature (TSR) Name (Print)	

DrägerService 3122 Commerce Drive Telford, PA 18969 Tel: (215) 721-5402 (800) 543-5047 Fax: (215) 723-5935

Web: www.draegermedical.com

DrägerService is a division of Draeger Medical, Inc.